

In-Field Steps to Take Down Counters

TRAFx Infrared Pedestrian Counters

1. Do not take counters down prior to one full week of data collection.
2. Record on the "Field Data Inventory Sheet" the exact time prior to starting the removal of the counters.
3. Remove counters using the drill and same drill bit used to install.
4. Return counters to H-GAC
5. Return/send filled out electronic "Field Data Inventory Sheet"
6. H-GAC will process the data within two weeks of receiving back the counters, and will send back to the city.

