

		SO2 Monitors (ppb)							
Date	Time	C45-1	C81-1	C403-2	C405-1	C406-1	C409-2	C416-1	C1022-1
1/18/2008	2:00	0	0.4	0.3	0.8	3.3	0.3	53.1	0.1
1/18/2008	3:00	0	0.3	1	1.6	2.3	0	61.8	0.4
1/23/2008	13:00	0	0.4	0	1	2.7	3.3	51.6	QAS
1/27/2008	6:00	0	0	0	0.7	12.8	13.5	82.8	0
1/27/2008	9:00	0.1	1.8	1	0.5	7.6	6.4	81.5	0
1/27/2008	13:00	0	76.2	32.7	1	6	22.6	13.1	0
1/27/2008	14:00	0	60.7	15.4	2.8	4.6	5.9	8.3	0.8
1/31/2008	3:00	0	52	1.8	2.3	0.7	0.8	1.6	0
4/14/2008	7:00	0	0.4	0.3	0.7	2.1	0.7	59.6	0
4/14/2008	8:00	0	0.4	0.3	0.4	3.9	0.4	59.2	0.1
5/16/2008	22:00	1	0	0	0	2.1	0	61.2	0
8/4/2008	8:00	1.8	0.2	0	0.7	0.2	9.4	63	3.5
9/4/2008	21:00	0.5	0	0	0.6	0.6	1	54.6	0
10/2/2008	10:00	2.2	1.7	56.1	10.5	3	3.5	3.6	4.9
10/18/2008	9:00	1.4	0	0	2	1.3	7.4	70.2	0.3
12/17/2008	11:00	1.5	50.1	3.1	1.3	PM	5.2	10	0
1/14/2009	10:00	1.8	66.9	21.3	9.2	5	5.2	4.4	3.2
3/3/2009	13:00	0.1	3.1	7.5	3	1.6	1.9	3.1	51.1
3/3/2009	14:00	0.2	3.3	10.1	3.1	1.4	1.3	2.7	93.3
3/3/2009	15:00	0.2	3.5	10.3	3.3	1.2	1	2.5	115.6
3/3/2009	16:00	0.1	10	12.1	3.9	0.8	1	2.4	108.1
3/3/2009	17:00	0.1	3.7	8.7	3.8	0.6	1	2.1	118.1
3/3/2009	18:00	0.1	2.1	11	3.2	0.6	0.7	2.2	65.4
3/3/2009	19:00	0.2	1.6	5	2.2	0.6	0.7	1.6	58.7
3/9/2009	16:00	0.7	0.3	0.3	1.4	0.2	0.3	0.6	76.1
3/30/2009	19:00	0	0.7	0	1.1	0.3	1.1	0.7	53.8
3/30/2009	20:00	0	0.7	0	1.2	0.1	1	0.9	61.3
4/4/2009	23:00	0	1.2	0	0.6	0.2	0.2	0.7	51.9
4/8/2009	8:00	0	0	58.1	0.8	0	0.3	0.2	3.1
4/25/2009	2:00	0	1.8	0	0.6	0	0.6	0.4	51.5
8/22/2009	12:00	2.6	0.6	1.9	122.2	0	0.1	0.6	3.9
10/25/2009	4:00	0	0.6	1.9	0	0.3	0	1.1	58.5
10/25/2009	7:00	0	0.6	0.8	0	0.4	0	1.1	53.4

50.0 - 74.9 ppb
75.0 - 99.9 ppb
100.0 - Over ppb